

Anleitung zum Laden: Wir empfehlen ein Ladegerät mit Ladestromerkennung. Verwenden Sie ein Ladegerät, das für das Laden von NiMH-Batterien zugelassen ist. Für maximale Gesamtlebensdauer der Batterie, laden Sie mit 3 A oder weniger. Für schnellstes Laden und maximale Leistung kann die Batterie mit 4 A geladen werden. Es ist normal, dass die Batterie gegen Ende des Ladevorgangs leicht warm wird. Sie sollte allerdings nie heiß werden. Wenn die Batterie heiß wird, trennen Sie sie unverzüglich vom Ladegerät.

[illegible]

Part # 2950X
Battery, Series 4
Power Cell (NIMH,
7-C-FLAT)

0 20334 1 29509 5

4200/194/400
NOD 794-400

Made in China, Manufactured in China,
Foxac, Wuxing, Jiang, Copyright © Foxac 2001

All rights reserved. Foxac's reserves, does its services, all rights reserved



***Auto Battery
Identification***

With iD Equipped Traxxas Chargers

Works with:



**Unmatched Charging
Safety and Simplicity**

Traxxas® iD™ chargers auto-detect
iD equipped Power Cell™ batteries
and automatically set and
optimize charge settings.